



INTELLIGENT
VIDEO

Firewall/router considerations for Teleprecision DVRs

To the unit on site:

Inbound to TCP 8524	ArcLite Review
Inbound to TCP 10191	ArcLite Live
Inbound to TCP 10192	Site Connection Monitor
Inbound to TCP 10193	SitePoint Live
Inbound to TCP 10194	SitePoint Review
Inbound to TCP 41777	Remote administration / configuration
Inbound to TCP 5900	Remote diagnostic
Outbound to TCP 25	Alarms out to Immix
Outbound to TCP 10192	Connection Verification
Outbound to TCP 59600	Alarms out to ArcLite

To the workstation at the central station:

Inbound to TCP 10192	Connection Verification
Inbound to TCP 59600	Alarms in to ArcLite

INTELLIGENT VIDEO LIMITED

REGISTERED ADDRESS

2 GAVESTON ROAD, ROYAL LEAMINGTON SPA
WARWICKSHIRE, CV32 6EU

T: 01926 523040 | F: 01926 523041 | E: SALES@INTELLIGENTVIDEO.TV

WWW.INTELLIGENTVIDEO.TV

COMPANY NUMBER 7220067 | VAT NUMBER GB987674149